



MS6208B

TACHOMETERS WITH DATA LOGGING

- Non-contact measurement of rotary speed
- **Data logging:** 100 groups of measures
- Data hold for easy reading
- Min /Max /Avg values measurement
- Auto zero adjustment
- 5 digits LCD display with backlit
- Low battery indication
- Auto power-off (in 30 sec.)
- Safety as per IEC1010-1

Technical specifications

Measuring range:

50~ 99,999 RPM

Measuring distance: 50~250mm

Resolution: 0.01RPM

Accuracy: $\pm 0.03\%$ +2dgt

Memories: 100 measures

Dimensions: 193x60x29mm, 120g approx.

Battery: 1.5Vx4, AAA size

Accessories: reflecting trips

PEAKMETER[®]

by Sinometer

www.peak-meter.cn

Email: sales@peak-meter.cn