

## PEAKMETER®

PM19 True RMS

## WORKSHOP DMM WITH TORCH LAMP

■ 6,000 counts LCD display with backlit

Non-Contact AC voltage detection in 3 levels

Audible continuity test in 3 levels
Extra bright torch lamp built on back

True RMS AC measurement (40Hz~1kHz)

Display frequency at ACV /ACA measurement
Data hold, auto ranging, auto power-off

10A/1000V fused, full ranges protection
Safety: Cat.III 1000V and Cat. IV 600V

Technical specifications DCV: 600m/6/60/600/1000V, ±0.5% ACV: 6/60/600/750V, ±0.8%

DCA: 60μ/600μ/6m/60m/600m/10A, ±0.8% ACA: 60μ/600μ/6m/60m/600m/10A, ±1.0% OHM: 600/6k/60k/60k/6M/60M Ω, ±0.8%

CAP:  $6n/60n/600n/6\mu/60\mu/600\mu/6m/100mF$ ,  $\pm 4.0\%$  TEMP:  $-20^{\circ}C \sim 1000^{\circ}C$ ,  $-4^{\circ}F \sim 1832^{\circ}F$ ,  $\pm 1.0\%$ 

FREQ: 10/100/1k/10k/100k/1M/10MHz, ±1.0% Duty cycle: 5%~95%, ±2.0%

Continuity:  $<40 \Omega$ ,  $40 \Omega \sim 60 \Omega$ ,  $>60 \Omega$ Diode test: 1 mA / 3.2 V

Dimensions & weight: 190x89x50mm, 380g approx. Battery: 1.5Vx4. AA size

Accessories: holster, temp probe

Email: sales@peak-meter.cn