



MS2101

1000A AC/DC DIGITAL CLAMP METER

- 4,000 counts LCD display
- Data hold and LCD back lighting
- Capacitance, temperature, frequency and duty cycle measurement
- Auto /manual ranging
- Safety as per IEC1010-1 Cat.II 1000V

Technical specifications

DCV: 400m/4/40/400/1000V, $\pm 0.7\%$

ACV: 4/40/400/750V, $\pm 0.8\%$

DCA: 400/1000A, $\pm 3.0\%$

ACA: 400/1000A, $\pm 3.0\%$

OHM: 400/4k/40k/400k/4M/40M Ω , $\pm 1.2\%$

CAP: 4n/40n/400n/4 μ /40 μ F, $\pm 4.0\%$

FREQ: 40/400/4k/40k/100kHz, $\pm 2.0\%$

TEMP: -40°C ~ 750°C , $\pm 1.0\%$

Duty cycle: 0.1%~99.9%

Audible continuity & diode test

Clamp size: $\phi 42\text{mm}$ (max.)

Dimensions: 250x99x43mm, 410g approx.

Battery: 9Vx1, 6F22

Accessories: carrying bag, temp. probe

PEAKMETER®

by Sinometer

www.peak-meter.cn

Email: sales@peak-meter.cn